Instructions

Step 1 - Safety

- · Unload the weapon
- Physically and visually inspect the chamber, bore, and magazine well to ensure that all ammunition has been removed.
- Store ammunition in an area that is separate from your training area.

 \triangle Always personally verify that all ammunition has been removed before training.

Do not allow any live ammunition in the training area.

Step 2 - Instillation - sleeve type

- Insert the SureStrike into the adaptor sleeve from the rimed side of the adaptor.
- 2 Make sure the SureStrik pushed all the way into the sleeve adaptor.

Step 2 - Instillation - Cap type

- 3 Unscrew the Cap from the Sure strike.
- 4 Connect the Adaptor cap to the laser by threading both parts together.



Full set of video instructions is available at: www.laser-ammo.com