Instructions

Step 1 - Safety

- Unload the weapon
- Physically and visually inspect the chamber, bore, and magazine well to ensure that all ammunition has been removed.
- Store ammunition in an area that is separate from your training area.

△ Always personally verify that all ammunition has been removed before training.

Do not allow any live ammunition in the training area.

Step 2 - Instillation - sleeve type

- Insert the SureStrike into the adaptor sleeve from the rimed side of the adaptor.
- 2 Make sure the SureStrik pushed all the way into the sleeve adaptor.

Step 2 - Instillation - Cap type

- 3 Unscrew the Cap from the Sure strike.
- 4 Connect the Adaptor cap to the laser by threading both parts together.







Full set of video instructions is available at: www.laser-ammo.com